FIGURE Defective Baxter Y-Type Blood/Solution Set with Pressure Pump

Examination of the manual pressure pump revealed that the seal between the top portion and the pump cylinder was flawed. Despite following manufacturer's recommendation the defect was undetected. Only if the pressure pump was held vertically and compressed against the closed regulating clamp distal to the pump could the defect be demonstrated.

Donald T. Jolly MD FRCPC
Edmonton, Alberta

REPLY:

We functionally qualify the hand pump to withstand internal pressure and typical manipulations that occur during compression of the hand pump. In addition, we conduct inspections of the pressure pump component and of the set.

The pressure that can be generated by the hand pump component is dependent on the stroke volume of the hand

pump, the inner diameter of distal components, the tubing dimensions, and length/modulus of elasticity. It is also dependent on the usage of the blood hand pump in terms of compressions per min. Other contributing factors may include fluid viscosity, surface characteristics of the tubing and components that might add resistance. The blood hand pump on the 2C7613 has a stroke volume between 26 and 29.5 ml.

We retrieved 50 unused samples of the reported product code from our manufacturing facility, testing was conducted, and no failures occurred. Components downstream of the hand pump can cause restriction and increased pressure. Thus, our label copy states, "The pressure pump is not recommended for use with products that have pressure limiting labeling statements and are used downstream of the pressure pump."

Debbie Lahr RN
IV Systems Division
Baxter Healthcare Corporation
Illinois, USA