

CORRIGENDUM

"Crack Growth Characteristics of an Epoxy Reinforced with Long Aligned Glass Fibers", J.Botsis and A.B. Shafiq, *International Journal of Fracture* 58 (1992) R3-R10.

It has been brought to our attention by the authors that Figures 8 and 9 were inadvertently omitted from the printing of the above referenced item. The Editorial Staff apologizes to the authors and readers who have been inconvenienced by our oversight. The appropriate figures and legends follow.




Figure 8. A schematic of fracture surfaces. The different shades indicate consecutive positions of the crack front.




Figure 9. Extent of fiber debonding for three fiber spacings.