

Edge chipping of brittle materials: effect of side-wall inclination and loading angle

Herzl Chai · Brian R. Lawn

Published online: 12 October 2007
© Springer Science+Business Media B.V. 2007

Erratum to: Int J Fract 145(2):159–165 (2007)
DOI 10.1007/s10704-007-9113-2

find on the following page the correct Figure 3 that should be regarded by the reader as the final version.

Due to an unfortunate turn of events this article has been published with an erroneous version of Figure 3. Please

The online version of the original article can be found under doi:[10.1007/s10704-007-9113-2](https://doi.org/10.1007/s10704-007-9113-2).

H. Chai
School of Mechanical Engineering, Faculty of Engineering,
Tel Aviv University, Tel Aviv, Israel

B. R. Lawn (✉)
Materials Science and Engineering Laboratory, National
Institute of Standards and Technology, Gaithersburg, MD,
20899-8520 USA
e-mail: brian.lawn@nist.gov

Fig. 3 Side views of Vickers cracks for normal loading ($\phi = 0$) on glass blocks with inclined side faces: **(a)** $\theta = -20^\circ$, $h = 0.8$ mm; **(b)** $\theta = +20^\circ$, $h = 1.0$ mm; **(c)** $\theta = +50^\circ$, $h = 2.2$ mm

