Author's Note: The author of "How To Select Axes for a Phase Diagram," in Vol. 18, No. 3, p 249, M. Hillert, has notified the staff of an error in the size of Fig. 7. The figure is shown below at the correct size.

Fig. 7 Stereographic pair showing the three-dimensional S_m, T, P property diagram for Fe. Only points on the marked surface have any meaning.