Also in Vol. 18, No. 3, p. 253 of the article by M. Hillert, "How To Select Axes for a Phase Diagram," Fig. 7 was not shown full size. It is shown below at 100% scale. The staff extends sincere apologies to Dr. Hillert.

Fig. 7 Stereographic pair showing the three-dimensional S_m, T, P property diagram for Fe. Only points on the marked surface have any meaning.