Erratum to: Are Quadrilateral Surface Buttress Plates Comparable to Traditional Forms of Transverse Acetabular Fracture Fixation?

Brian J. Kistler MD, Ian R. Smithson MD, Seth A. Cooper MD,
Jacob L. Cox MD, Aniruddh N. Nayak MS, Brandon G. Santoni PhD,
H. Claude Sagi MD

Published online: 18 October 2014
© The Association of Bone and Joint Surgeons® 2014

Erratum to: Clin Orthop Relat Res (2014) 472:3353–3361 DOI 10.1007/s11999-014-3800-x

In the published study, “Are Quadrilateral Surface Buttress Plates Comparable to Traditional Forms of Transverse Acetabular Fracture Fixation?” the captions for figures 1C–D and 5C–D are incorrect. For Figure 1C–D, the captions should read: “(C) a suprapectineal posterior column/quadrilateral surface buttress plate; and (D) a 10-hole

anterior column pelvic reconstruction buttress plate supplemented with an infrapectineal quadrilateral surface buttress plate.

For Figure 5C–D, the captions should read: (C) suprapectineal, and (D) infrapectineal fixation. The failure mechanism of the lag screw constructs is depicted in Fig. 3.

The authors apologize for these errors.

The online version of the original article can be found under doi:[10.1007/s11999-014-3800-x](https://doi.org/10.1007/s11999-014-3800-x).

B. J. Kistler, H. C. Sagi (✉)
Orthopaedic Trauma Service, Florida Orthopaedic Institute,
5 Tampa General Circle, Suite 710, Tampa, FL 33606, USA
e-mail: eversosaggy@me.com

I. R. Smithson, S. A. Cooper, B. G. Santoni
Department of Orthopaedic Surgery & Sports Medicine,
University of South Florida, Tampa, FL, USA

J. L. Cox, A. N. Nayak, B. G. Santoni
Phillip Spiegel Orthopaedic Research Laboratory, Foundation
for Orthopaedic Research & Education, Tampa, FL, USA