Erratum

Erratum to “Study on hot rolling process of the D51 large-diameter threaded bars” [32 (4) (2018) 1761~1768][†]

Jeong-min Kim¹, Sung-bin Won² and Byung-min Kim^{3,*}

¹Dept. of Precision Manufacturing Systems Engineering, Pusan National University, Busan, Korea

²R&D Center, Dongkuk Steel Co., Ltd, Pohang, Korea

³School of Mechanical Engineering, Pusan National University, Busan, Korea

There are two corrections to make to the original article.

1) A part of Figure 7 has appeared in Figure 8 inadvertently. The Figure 7 and 8 should be corrected as follows:

Fig. 7. Strain in the -y direction of the D51 threaded bar after final rolling pass: (a) Case 1; (b) case 2; (c) case 3; (d) case 4; (e) case 5; (f) case 6.

Fig. 8. Prediction results using ANN: (a) Width of the core part; (b) height of the transverse rib.

2) Some of the reference numbers in the text were misprinted. The reference numbers should be corrected as follows:

- Page 1762, left column, 11th line from bottom: The reference number should be [6, 17-19], not [8-11]
- Page 1764, right column, 9th line from bottom: The reference number should be [12], not [9]
- Page 1764, right column, 13th line from bottom: The reference number should be [12], not [9]
- Page 1767, Table 10: The reference number should be [11], not [20]

† DOI of the original article: DOI 10.1007/s12206-018-0332-4

* Corresponding author. Tel.: +82 51 510 3074, Fax.: +82 51 580 3075

E-mail address: bmkim@pusan.ac.kr

† Recommended by Associate Editor Dae-Cheol Ko

© KSME & Springer 2018