Erratum to: Effect of Process Parameters on the Interface Microstructure and Thickness of Silver Cladding Copper Wires Prepared by Core-Cladding Continuous Casting

Feng Yi, Xuefeng Liu and Yue Pan

Erratum to:
Chapter “Effect of Process Parameters on the Interface Microstructure and Thickness of Silver Cladding Copper Wires Prepared by Core-Cladding Continuous Casting” in:
Y. Han (ed.), *Advances in Materials Processing*, Lecture Notes in Mechanical Engineering,
https://doi.org/10.1007/978-981-13-0107-0_20

The original version of the book was inadvertently published with incorrect temperature ranges in chapter “Effect of Process Parameters on the Interface Microstructure and Thickness of Silver Cladding Copper Wires Prepared by Core-Cladding Continuous Casting”, which have to be now corrected. The erratum chapter and the book have been updated with the changes.

The updated online version of this chapter can be found at
https://doi.org/10.1007/978-981-13-0107-0_20

© Springer Nature Singapore Pte Ltd. 2018
Y. Han (ed.), *Advances in Materials Processing*, Lecture Notes in Mechanical Engineering, https://doi.org/10.1007/978-981-13-0107-0_124

E1