Corrections · Berichtigungen

Rheol. Acta **17**, 698 (1978)

© 1978 Dr. Dietrich Steinkopff Verlag, Darmstadt

ISSN 0035-4511 / ASTM-Coden: RHEAAK

Errata to Non-Newtonian fluid flow between rotating cylinders

G. Ehrmann, R. Takserman-Krozer, and G. Schenkel

Rheol. Acta **16**, 240–247 (1977)

(Received November 14, 1978)

In this paper the following misprints have to be corrected:

1. Eq. [11] should be

$$\eta = \eta_{\infty} = \frac{1}{\sum_{i=0}^{\infty} a_i \tau^{2i}}.$$

2. The graphs corresponding to the titles 7 and 11 have to be exchanged.

Authors' addresses:

Dr.-Ing. *G. Ehrmann*
BASF Aktiengesellschaft
TET/VK 1, L 544
D-6700 Ludwigshafen

Prof. Dr. *R. Takserman-Krozer*
Institut für Theoretische und Angewandte Physik
Pfaffenwaldring 57
D-7000 Stuttgart 80

Prof. Dr.-Ing. *G. Schenkel*
Institut für Kunststofftechnologie
Böblinger Straße 70
D-7000 Stuttgart 1