8. K. R. Evans: *Trans. TMS-AIME*, 1968, vol. 242, p. 648.

9. H. Conrad: *Acta Met.*, 1966, vol. 14, p. 1631.

10. H. Conrad: *J. Can. Phys.*, 1967, vol. 45, p. 581.

11. H. Conrad and R. Jones: *The Science and Technology of Titanium*, p. 489, Pergamon Press, 1970.

12. K. V. Ravi and R. Gibala: *Met. Trans.*, 1971, vol. 2, p. 1219.

13. F. Kocks: Presented at the Fall Meeting of AIME, Philadelphia, Pa., Oct., 1969.

14. C. N. Ahlquist: *Scripta Met.*, 1971, vol. 5, p. 185.

Corrections to *Met. Trans.*, 1973, vol. 4

Diffusion of Hydrogen in Titanium Alloys Due to Composition, Temperature, and Stress Gradients, by J. L. Waisman, George Sines, and L. B. Robinson, pp. 291-302

Page 300, Equation [2.8]

The number 3 was omitted from the denominator of this equation. The equation should read:

$$J_m = -D \left[\frac{dC_m}{dx} + 3.55C_m \frac{dN_{AL}}{dx} - \frac{2.0C_m}{3RT} \frac{d\tau}{dx} + \frac{(5300 - 583N_{AL})}{RT^2} C_m \frac{dT}{dx} \right] \quad [2.8]$$

An Analysis of Plastic Instability in Pure Shear in High Strength AISI 4340 Steel, by Kohichi Tanaka and Joseph W. Spretnak, pp. 443-54

Page 443

The equation on page 443 should read:

$$d\sigma = \left(\frac{\partial \sigma}{\partial \epsilon} d\epsilon + \frac{\partial \sigma}{\partial \dot{\epsilon}} d\dot{\epsilon} + \frac{\partial \sigma}{\partial T} dT \right) = 0$$