Erratum to: A Case of Late Femoral Pseudoaneurysm Caused by Stent Disconnection

Nicola Rivolta · Federico Fontana · Gabriele Piffaretti ·
Matteo Tozzi · Gianpaolo Carrafiello

Published online: 5 February 2010

© Springer Science+Business Media, LLC and the Cardiovascular and Interventional Radiological Society of Europe (CIRSE) 2010

Erratum to: *Cardiovasc Intervent Radiol* DOI 10.1007/s00270-009-9677-5

This article described the use of three overlapped 8×80 -mm “nitinol” stents (Wallstent; Boston Scientific, Natick, MA, USA) placed in the left SFA. Please note that

Wallstent is not made of nitinol, and is a self-expanding stent composed of biomedical grade cobalt–chromium–iron–nickel–molybdenum alloy wires (commonly known as Elgiloy or Conichrome) braided in a tubular mesh configuration. Nitinol stents and elgiloy stents consist of different features and properties. We regret this oversight.

The online version of the original article can be found under doi:[10.1007/s00270-009-9677-5](https://doi.org/10.1007/s00270-009-9677-5).

N. Rivolta · G. Piffaretti (✉) · M. Tozzi
Department of Surgical Sciences, Vascular Surgery,
Varese University Hospital, University of Insubria,
Via Guicciardini 9, 21100 Varese, Italy
e-mail: gabriele.piffaretti@uninsubria.it

F. Fontana · G. Carrafiello
Department of Radiology, Interventional Radiology,
Varese University Hospital, University of Insubria,
Varese, Italy