ERRATUM

To the article “Problems in Studying Formation of Smoke Oxide Particles in Combustion of Aluminized Solid Propellants” by V. A. Babuk, published in *Combustion, Explosion, and Shock Waves*, Vol. 43, No. 1, pp. 38–45, 2007.

Page 41 contains a misprint: Table 1, column 3 should be “ d_{43} , nm” instead of “ d_{43} , μm .”