ERRATA

In the article on Dump Slope Stability Analysis – A Case Study by Prasanta Kumar Behera, Kripamoy Sarkar, Ashok Kumar Singh, A.K. Verma and T.N. Singh published in December 2016 issue (pp.725-735) of the Journal, the following errors have inadvertently crept in. Readers are requested to make a note of the following changes.

On page 727, Figure 4 caption should read as 'Production of Coal and OB at Bhubaneswari OCP'.

On page 728, Fig.6 is repeated as Figure 7 and should be replaced with the below given figure.

Fig.7. SEM photomicrograph of Shale