Correction to: Automatic monitoring of steel strip positioning error based on semantic segmentation

Aline de Faria Lemos¹ · Leonardo Adolpho Rodrigues da Silva² · Balázs Vince Nagy¹

Published online: 15 September 2020

© Springer-Verlag London Ltd., part of Springer Nature 2020

Correction to: The International Journal of Advanced Manufacturing Technology
<https://doi.org/10.1007/s00170-020-05859-w>

The original published article contained a mistake.

Table 1 contains errors. Please find the correct version of the referred table below.

The online version of the original article can be found at <https://doi.org/10.1007/s00170-020-05859-w>

✉ Aline de Faria Lemos
alinefaria@mogi.bme.hu

Leonardo Adolpho Rodrigues da Silva
leonardo@ufsj.edu.br

Balázs Vince Nagy
nagyb@mogi.bme.hu

¹ Department of Mechatronics, Optics and Mechanical Engineering Informatics, Budapest University of Technology and Economics, Budapest, Hungary

² Department of Telecommunications and Mechatronics Engineering, Federal University of São João del-Rei, Ouro Branco, Brazil

Table 1 Models parametrization

Model ID	Architecture	Number of filters	Kernel size	Downsampling			Upsampling		
				Layer 1 Pooling/stride	Layer 2 Pooling/stride	Layer 3 Pooling/stride	Layer 3 Upsampling factor	Layer 2 Upsampling factor	Layer 1 Upsampling factor
1	1	2	3×3	2/2	—	—	—	—	2
2	1	4	3×3	2/2	—	—	—	—	2
3	1	8	3×3	2/2	—	—	—	—	2
4	1	16	3×3	2/2	—	—	—	—	2
5	1	32	3×3	2/2	—	—	—	—	2
6	1	64	3×3	2/2	—	—	—	—	2
7	2	2	3×3	2/2	2/2	—	—	2	2
8	2	4	3×3	2/2	2/2	—	—	2	2
9	2	8	3×3	2/2	2/2	—	—	2	2
10	2	16	3×3	2/2	2/2	—	—	2	2
11	2	32	3×3	2/2	2/2	—	—	2	2
12	2	64	3×3	2/2	2/2	—	—	2	2
13	3	2	3×3	2/2	2/2	3/3	3	2	2
14	3	4	3×3	2/2	2/2	3/3	3	2	2
15	3	8	3×3	2/2	2/2	3/3	3	2	2
16	3	16	3×3	2/2	2/2	3/3	3	2	2
17	3	32	3×3	2/2	2/2	3/3	3	2	2
18	3	64	3×3	2/2	2/2	3/3	3	2	2

The original article has been corrected.

Publisher's note Springer Nature remains neutral with regard to jurisdictional claims in published maps and institutional affiliations.