Correction to: Limitations of $Sa(T_1)$ as an intensity measure when assessing non-ductile infilled RC frame structures

Gerard J. O'Reilly¹

Published online: 6 April 2021
© Springer Nature B.V. 2021

Correction to: Bulletin of Earthquake Engineering
<https://doi.org/10.1007/s10518-021-01071-7>

Proofing error was noticed in Fig. 2a, b and have been thus updated with the ones submitted initially as follows:

Original article has been updated.

The original article can be found online at <https://doi.org/10.1007/s10518-021-01071-7>.

✉ Gerard J. O'Reilly
gerard.oreilly@iusspavia.it

¹ Scuola Universitaria Superiore IUSS Pavia, Piazza della Vittoria 15, 27100 Pavia, Italy

Fig. 2 Set of 40 ground motion records selected for the RC-WI-3 structure at the 2% in 50 years probability of exceedance for (top) $Sa(T_1=0.37$ s) and (bottom) $AvgSa$, where matching of the selected mean and dispersion is compared to the targeted distribution. The red shaded zones indicate the conditioning period value (or range) used

Publisher's Note Springer Nature remains neutral with regard to jurisdictional claims in published maps and institutional affiliations.