Correction to: Formation of brominated and chlorinated dioxins and its prevention during a pilot test of mechanochemical treatment of PCB and PBDE contaminated soil

Mengnan Lu¹ · Tianwu Lv² · Ying Li³ · Zheng Peng³ · Giovanni Cagnetta¹ · Shouxiang Sheng² · Jun Huang¹ · Gang Yu¹ · Roland Weber⁴

Published online: 18 April 2018

© Springer-Verlag GmbH Germany, part of Springer Nature 2018

Correction to: Environ Sci Pollut Res (2017) 24:20072–20081
(<https://doi.org/10.1007/s11356-017-9574-4>)

The original publication contains an error in Fig. 4.
The correct fig. 4(a) PBDD is included below in this Erratum.

Fig. 4 Concentration of homologs formed from BDE-209 under different water-cooling system. a PBDD

The online version of the original article can be found at <https://doi.org/10.1007/s11356-017-9574-4>

✉ Jun Huang
huangjun@tsinghua.edu.cn

¹ School of Environment, Beijing Key Laboratory for Emerging Organic Contaminants Control, Key Laboratory of Solid Waste Management and Environment Safety (Tsinghua University), Ministry of Education, Tsinghua University, Beijing 100084, China

² CSD Emerging Environmental Technology Center (CETC) (Beijing) Co. Ltd., Beijing 100192, China

³ Foreign Economic Cooperation Office, Ministry of Environmental Protection, Beijing 100035, China

⁴ POPs Environmental Consulting, Lindenfirststr. 23, 73527 SchwäbischGmünd, Germany