Erratum to: Settlement patterns of mountainous half-filled and half-cut widened subgrade with retaining wall

FU Yong-guo^{1,2,3} <https://orcid.org/0000-0003-1416-5992>; e-mail: 809107486@qq.com

JIANG Xin^{1,2,3*} <https://orcid.org/0000-0002-3044-5495>; e-mail: xjiang01@163.com, xjiang01@swjtu.edu.cn

GU Han-yan^{1,2,3} <https://orcid.org/0000-0003-2881-6282>; e-mail: 893634386@qq.com

QIU Yan-jun^{1,2,3} <https://orcid.org/0000-0002-2250-5363>; e-mail: publicqiu@vip.163.com

**Corresponding author*

1 School of Civil Engineering, Southwest Jiaotong University, Chengdu 610031, China

2 MOE Key Laboratory of High-speed Railway Engineering, Southwest Jiaotong University, Chengdu 610031, China

3 Highway Engineering Key Laboratory of Sichuan Province, Southwest Jiaotong University, Chengdu 610031, China

Citation: Fu YG, Jiang X, Gu HY, Qiu YJ (2021) Erratum to: Settlement patterns of mountainous half-filled and half-cut widened subgrade with retaining wall. Journal of Mountain Science 18(12). <https://doi.org/10.1007/s11629-020-6267-0>

© Science Press, Institute of Mountain Hazards and Environment, CAS and Springer-Verlag GmbH Germany, part of Springer Nature 2021

Erratum to: J. Mt. Sci. (2021) 18(10): 2791-2802 <https://doi.org/10.1007/s11629-020-6551-z>

The numbers of four figures in the figure captions are wrong.

On Page 2797, the figure's number in the figure caption should be [Fig. 6](#).

On Page 2798, the figure's number in the figure caption should be [Fig. 7](#).

On Page 2799, the figure's number in the figure caption should be [Fig. 8](#).

On Page 2801, the figure's number in the figure caption should be [Fig. 11](#).

The online version of the original article can be found
at <https://doi.org/10.1007/s11629-020-6551-z>