Correction to: Long-Term Creep-Rupture Behavior of Alloy Inconel 740/740H

M. RENDER, M.L. SANTELLA, X. CHEN, P.F. TORTORELLI, and V. CEDRO III

<https://doi.org/10.1007/s11661-021-06342-1>

© The Minerals, Metals & Materials Society and ASM International 2021

Correction to: Metallurgical and Materials Transactions A, Volume 52A, June 2021

<https://doi.org/10.1007/s11661-021-06253-1>

Publisher's Note Springer Nature remains neutral with regard to jurisdictional claims in published maps and institutional affiliations.

IN the original online version of the article the reference citations in Table VII were incorrect. The original article was corrected.

M. RENDER is with the National Energy Technology Laboratory, Morgantown, WV 26507. Contact e-mail: Mark.Render@netl.doe.gov M.L. SANTELLA and P.F. TORTORELLI are with the Materials Science and Technology Division, Oak Ridge National Laboratory, Oak Ridge, TN 37831. Contact e-mail: tortorellipf@ornl.gov X. CHEN is with the Materials Science and Technology Division, Oak Ridge National Laboratory. V. CEDRO III is with the National Energy Technology Laboratory, Pittsburgh, PA 15236.

The original article can be found online at <https://doi.org/10.1007/s11661-021-06253-1>.

Article published online June 11, 2021