CORRECTION

Correction to: Microbiologically Influenced Corrosion of AA 6061 with *Bacillus* Species in an Environment Containing an Organic Nitrogen Source

Ziheng Bai, Kui Xiao, Qiong Yao, Chaofang Dong, Dongjiu Zhang, Junsheng Wu, and Shiwen Zou

Published online: 29 November 2021

Correction to:

JMEPEG

<https://doi.org/10.1007/s11665-021-06379-8>

In the originally published article, Figure 5 showed a copy of Figure 4. The article has been updated to correct this error, and the correct images for Fig. 5 are shown below.

The original article can be found online at <https://doi.org/10.1007/s11665-021-06379-8>.

Ziheng Bai, Kui Xiao, Chaofang Dong, and Junsheng Wu, Institute for Advanced Materials and Technology, University of Science and Technology Beijing, Beijing 100083, People's Republic of China; and National Materials Corrosion and Protection Data Center, University of Science and Technology Beijing, Beijing 100083, People's Republic of China; **Qiong Yao and Dongjiu Zhang**, Key Laboratory of Space Launching Site Reliability Technology, Haikou 571000, People's Republic of China; **Shiwen Zou**, Aerospace Research Institute of Materials and Processing Technology, Beijing 100076, People's Republic of China. Contact e-mail: xiaokui@ustb.edu.cn.

Figure 5 SEM of aluminum alloy 6061 in low nutrient concentration with bacteria after (a) 2 days, (b) 5 days, (c) 8 days, and (d) 13 days

Publisher's Note Springer Nature remains neutral with regard to jurisdictional claims in published maps and institutional affiliations.