CORRECTION

Correction to: Locator Placement Optimization for Minimum Part Positioning Error During Machining Operation Using Genetic Algorithm

Sajid Ullah Butt¹ · Mamoon Arshad¹ · Aamer Ahmed Baqai¹ · Hasan Aftab Saeed¹ · Naveed Akmal Din¹ · Rehan Ahmed Khan¹

Published online: 16 April 2021

© Korean Society for Precision Engineering 2021

Correction to:
International Journal of Precision Engineering and Manufacturing
<https://doi.org/10.1007/s12541-021-00500-6>

Due to an unfortunate oversight the Figs. 19 and 20 are the same. They should be as follows:

Fig. 19 ANSYS result: locators are placed according to Table 7 and force is applied at P_1

Fig. 20 ANSYS result: locators are placed according to Table 7 and force is applied at P_2

Publisher's Note Springer Nature remains neutral with regard to jurisdictional claims in published maps and institutional affiliations.

The original article can be found online at <https://doi.org/10.1007/s12541-021-00500-6>.

✉ Sajid Ullah Butt
sajidullahbutt@ceme.nust.edu.pk
Mamoon Arshad
mamoon_arshad76@me.ceme.edu.pk
Aamer Ahmed Baqai
aamer.baqai@ceme.nust.edu.pk
Hasan Aftab Saeed
hasan.saeed@ceme.nust.edu.pk

Naveed Akmal Din
naveeddin@ceme.nust.edu.pk
Rehan Ahmed Khan
rehan.ahmed@ceme.nust.edu.pk

¹ Department of Mechanical Engineering (CEME), National University of Sciences and Technology (NUST), Sector H-12, Islamabad 4600, Pakistan