Correction to: Imbalance phenomenon caused by CPS-PWM strategy for MMC Systems

Chuyang Wang¹ · Li Zhang¹ · Zitao Zhang¹ · Yicheng Tao¹

Published online: 19 November 2020
© The Korean Institute of Power Electronics 2020

Correction to: Journal of Power Electronics
<https://doi.org/10.1007/s43236-020-00165-w>

Due to an unfortunate oversight the funding number of the Fundamental Research Funds for the Central Universities has been given erroneously. It should be read: 2013/2019B04114.

The original article can be found online at <https://doi.org/10.1007/s43236-020-00165-w>.

✉ Li Zhang
zhanglinuaa@hhu.edu.cn

¹ College of Energy and Electrical Engineering, Hohai University, Nanjing, China