ERRATA

**Erratum to: “Development and Application
of an Information—Analytic System on the Problem of Flow
Accelerated Corrosion of Pipeline Elements in the Secondary Coolant
Circuit of VVER-440-Based Power Units at the Novovoronezh
Nuclear Power Plant” [Thermal Engineering 62, 138 (2015)]**

**G. V. Tomarov^a, V. P. Povarov^b, A. A. Shipkov^a, A. F. Gromov^b, A. N. Kiselev^b,
S. V. Shepelev^a, and A. V. Galanin^b**

^a*Geotherm-EM, ul. Lefortovskii Val 24, Moscow, 111250 Russia*

^b*Novovoronezh Nuclear Power Plant, Novovoronezh, Voronezh oblast, 396072 Russia*

e_mail: geotherm@gmail.com

DOI: 10.1134/S0040601516070090

(Submitted March 31, 2016; accepted for publication March 31, 2016)

Page 139, left column, second paragraph from bottom, second sentences should read:

In 2013, the RAMEK-1 software tool was qualified at Rostekhnadzor (the Federal Service of Russia for Environmental, Technological, and Nuclear Supervision) (the Software Tool Certificate No. 331) for calculating corrosion rate in elements of pipelines and equipment used in the condensate feedwater path of VVER-based NPP power units.

The authors and the editors apologize for inaccuracies.