INFORMATION

Errata: “Formation of Tin Oxides in Thin-Film Sn/C/KCl(100) Structures”

[*Crystallogr. Rep.* 54 (1), 110 (2009)]

**Yu. A. Yurakov, S. V. Ryabtsev, O. A. Chuvenkova, E. P. Domashevskaya,
A. S. Nikitenko, S. V. Kanykin, and S. B. Kushchev**

PACS numbers: 01.60.+q

DOI: 10.1134/S1063774509040336

(i) Throughout the text, $\text{SnO}_2(\text{O})$ should be read instead of $\text{SnO}_2(\text{P})$.

(ii) In Fig. 2e, $\text{SnO}_2(\text{T})$ should have been written above the top row of interplanar spacings and $\text{SnO}_2(\text{O})$ should be read instead of $\text{SnO}_2(\text{T})$ in the left bottom row of interplanar spacings.

(iii) In Fig. 3a, $\text{SnO}_2(\text{O})$ should be read instead of $\text{SnO}_2(\text{T})$ under the left bottom row of interplanar spacings.

(iv) In Fig. 4c, $\text{SnO}(\text{T})$ should be read instead of $\text{SnO}(\text{O})$ under the right bottom row of interplanar spacings.