

# ERRATUM

## Chapter 2 Methods of Photometric and Radiometric Measurements

M. Bukshtab, *Applied Photometry, Radiometry, and Measurements of Optical Losses*,  
Springer Series in Optical Sciences 163, DOI 10.1007/978-94-007-2165-4,  
©Springer Science+Business Media B.V. 2012

---

**DOI 10.1007/978-94-007-2165-4\_12**

In equations (2.1)–(2.3) the square-power index <sup>2</sup> for current J was misplaced.  
Correct equations are:

$$Q_0\alpha = J^2Rt = \frac{\partial}{\partial T}(CV\Delta T), \quad (2.1)$$

$$\Phi_0\alpha = J^2R = qA_\Sigma\Delta T. \quad (2.2)$$

$$Q = \varepsilon J^2Rt; \quad \Phi = \varepsilon J^2R \quad (2.3)$$