

# Erratum

0960–3182/92 © 1992 Chapman & Hall

*Geotechnical and Geological Engineering*, 1992, 10, 61–86

ATTEWELL, P.B., SELBY, A.R. and O'DONNELL, L.

**Tables and graphs for the estimation of ground vibration from driven piling operations**

Figures 1–6 were printed incorrectly. The correct figures and captions are as follows.




Fig. 1. Impact hammers – best estimate




Fig. 2. Impact hammers – plus half std dev.




Fig. 3. Impact hammers – plus one std dev.




Fig. 4. Vibrodrivers – best estimate




Fig. 5. Vibrodrivers – plus half std dev.




Fig. 6. Vibrodrivers – plus one std dev.