

ERRATA

Standards of Electrical Units and the Transfer of their Dimensions
to Measures and Instruments by N. L. Amatuni et al. [Measurement Techniques, No. 11,
1395-1401 (1967)]

On p. 1396, in the equation on line 3, $A = LT^2/\omega$ should read $A = LI^2/2$.