



CORRECTION

## Correction to: Study on surface quality of laser cleaning of oxide film on nickel-base superalloy

Wei Wang<sup>1</sup> · Xiaoyu Wang<sup>1</sup> · Weijun Liu<sup>1</sup> · Fei Xing<sup>1</sup> · Xianmin Zhou<sup>2</sup> · Lei Zhang<sup>2</sup>

Published online: 22 March 2022

© The Author(s), under exclusive licence to Springer-Verlag GmbH, DE part of Springer Nature 2022

**Correction to: Applied Physics A (2022) 128:247**  
<https://doi.org/10.1007/s00339-022-05388-1>

In the original publication of the article, Table 1 was incorrect. The correct Table 1 appears as below.

It will not have any impact on the analysis of the article and the conclusion of the article.

**Publisher's Note** Springer Nature remains neutral with regard to jurisdictional claims in published maps and institutional affiliations.

**Table 1** Laser cleaning test parameters

Laser parameters	Symbol	Numerical value
Scanning speed (mm/s)	$v$	6000, 7000, 8000, 9000, 10000
Spot overlap rate (%)	$U_p$	62.5, 56.25, 50, 43.75, 37.5
Pulse width (ns)	$t$	60
Cleaning power (W)	$p$	50–200
Spot diameter (mm)	$d$	0.8
Repetition rate (kHz)	$f$	20

The original article can be found online at <https://doi.org/10.1007/s00339-022-05388-1>.

✉ Wei Wang  
wangwei\_me@sut.edu.cn

✉ Weijun Liu  
wjliu@sut.edu.cn

<sup>1</sup> School of Mechanical Engineering, Shenyang University of Technology, Shenyang 110870, People's Republic of China

<sup>2</sup> Shenyang Pakalajing Co., Ltd, Shenyang 110042, People's Republic of China