

## Erratum to: Meso-scale analysis on shear failure characteristics of asphalt–aggregate interface

Xin Qiu  · Shanglin Xiao · Qing Yang · Yujie Wang · Feng Wang

Published online: 2 October 2017  
© RILEM 2017

**Erratum to: Materials and Structures (2017) 50:209**  
**DOI 10.1617/s11527-017-1075-x**

Due to an unfortunate turn of events, this article was published with an erroneous version of Fig. 3. The

thickness of the steel plate should be 4 (mm) instead of 40 (mm). Please find in this erratum the correct version of Fig. 3 that should be regarded as final version by the reader.

---

The online version of the original article can be found under doi:[10.1617/s11527-017-1075-x](https://doi.org/10.1617/s11527-017-1075-x).

---

X. Qiu (✉) · S. Xiao · Q. Yang · Y. Wang  
College of Engineering, Zhejiang Normal University,  
Jinhua 321004, China  
e-mail: xqiu@zjnu.cn

S. Xiao  
e-mail: zjnuxsl@gmail.com

Q. Yang  
e-mail: yangq@zjnu.cn

Y. Wang  
e-mail: wyj@zjnu.net

F. Wang  
Department of Civil and Environmental Engineering,  
Jackson State University, Jackson 39204, USA  
e-mail: feng.wang@jsum.edu

**Fig. 3** Direct shear test apparatus (dimensions in mm)

