

ERRATUM

# Light induced silver and copper plating on silver screen-printed contacts of silicon solar cells


S. TUTASHKONKO<sup>1,2</sup>, A. KAMINSKI-CACHOPO<sup>1</sup>, C. BOULORD<sup>1</sup>, R. ARS<sup>2</sup>, V. AIMEZ<sup>2</sup>, and M. LEMITI<sup>1</sup>

<sup>1</sup>Institut des Nanotechnologies de Lyon INL-UMR5270, Universite de Lyon, CNRS, INSA de Lyon, Villeurbanne, F-69621, France



<sup>2</sup>CRN2, Universite de Sherbrooke Sherbrooke, Quebec, Canada J1K 2R1

[OPTO-ELECTRONICS REVIEW 19(3), 301–306 (2011) ]



In the paper the following errors are found:





p. 303  
Figure 4



p. 304  
Figure 5



p. 304  
Figure 6



p. 305  
Figure 7

