

Structure and operation strategies of an automatic supervisory control system for the KEPCO UPFC

Seon-Ju Ahn · Dong-Woo Lee · Seung-II Moon

Published online: 9 August 2008
© Springer-Verlag 2008

Erratum to: Electr Eng
DOI 10.1007/s00202-008-0100-z

The original version of this article unfortunately contained a mistake. The presentation of Fig. 5 was incorrect. The correct figure is given below.




Fig. 5 Flowchart of the operation algorithm in the normal state

The online version of the original article can be found under doi:[10.1007/s00202-008-0100-z](https://doi.org/10.1007/s00202-008-0100-z).

S.-J. Ahn (✉) · D.-W. Lee · S.-I. Moon
Seoul National University, Seoul, South Korea
e-mail: lion52@powerlab.snu.ac.kr