



Correction to: Shear Rate Effects on the Post-peak Shear Behaviour and Acoustic Emission Characteristics of Artificially Split Granite Joints

Fanzhen Meng^{1,2} · Louis Ngai Yuen Wong² · Hui Zhou³ · Jin Yu⁴ · Guangtan Cheng³

Published online: 31 May 2019
© Springer-Verlag GmbH Austria, part of Springer Nature 2019

Correction to: Rock Mechanics and Rock Engineering
<https://doi.org/10.1007/s00603-018-1722-8>

This paper, not properly checked by the authors when receiving the proofs, is in need of corrections as indicated below.

In the legends of Figs. 12a and 13a, the “energy rate 1, energy rate 2, energy rate 3, energy rate 4” should be “hit rate 1, hit rate 2, hit rate 3, hit rate 4”.

The original article can be found online at <https://doi.org/10.1007/s00603-018-1722-8>.

✉ Louis Ngai Yuen Wong
Inywong@hku.hk

- ¹ College of Science, Qingdao University of Technology, Qingdao 266033, Shandong, China
- ² Department of Earth Sciences, The University of Hong Kong, Pokfulam, Hong Kong, China
- ³ State Key Laboratory of Geomechanics and Geotechnical Engineering, Institute of Rock and Soil Mechanics, Chinese Academy of Sciences, Wuhan 430071, Hubei, China
- ⁴ Institute of Geotechnical Engineering, Hua Qiao University, Xiamen, China