CORRECTION

Correction to: Discontinuum analysis of the fracture mechanism in masonry prisms and wallettes via discrete element method

Bora Pulatsu · Ece Erdogan · Paulo B. Lourenço · Jose V. Lemos · Jim Hazzard

Published online: 30 April 2020
© Springer Nature B.V. 2020

find in this document the correct version of Fig. 11 that should be regarded as the final version by the reader.

Correction to: Meccanica (2020) 55:505–523
<https://doi.org/10.1007/s11012-020-01133-1>

Due to an unfortunate turn of events, this article was published with an erroneous version of Fig. 11. Please

The original article can be found online at <https://doi.org/10.1007/s11012-020-01133-1>.

B. Pulatsu (✉) · E. Erdogan
Architectural Engineering, University of Nebraska-
Lincoln, Lincoln, USA
e-mail: bpulatsu@unomaha.edu

P. B. Lourenço
Institute for Sustainability and Innovation in Structural
Engineering, University of Minho, Guimaraes, Portugal

J. V. Lemos
Laboratório Nacional de Engenharia Civil, Lisbon,
Portugal

J. Hazzard
Itasca Consulting Group, Minneapolis, USA

Fig. 11 Failure mechanism mode 1; left: experiment [25], right: numerical prediction

Publisher's Note Springer Nature remains neutral with

regard to jurisdictional claims in published maps and institutional affiliations.