



# Seismic vulnerability assessment and fragility curves for a multistorey gallery arch bridge

Vinay Shimpi<sup>1</sup> · Madappa V. R. Sivasubramanian<sup>1</sup> · S. B. Singh<sup>2</sup> · D. Kesavan Periyasamy<sup>1</sup>

Received: 19 September 2020 / Accepted: 11 May 2021

Published online: 26 May 2021

© The Author(s) 2021 [OPEN](#)

## Abstract

The masonry bridges on the Kalka Shimla Mountain Railway line, which have multiple arch galleries in the form of Roman aqueducts, are spectacular. The Kalka Shimla Mountain Railway line is situated in severe seismic zones (Indian Standard 1893:2016). This research assesses the seismic vulnerability of masonry arch Bridge No. 541 situated on the Kalka Shimla Mountain Railway line. This bridge is the tallest on the route. In particular, it assesses the seismic vulnerability of the bridge using finite element (FE) analysis. For this purpose, an FE model for the bridge is developed using the ABAQUS FE-based environment. The experimental field study conducted on the bridge using an ambient vibration test (AVT) and dynamic parameters (frequency and mode shapes) is evaluated by operational modal analysis (OMA). Further, the FE model is updated by modifying the elastic mechanical property of the stone masonry to match the analytical modal frequency with the results of the AVT and OMA. The updated model is then used to perform a pushover analysis and nonlinear dynamic analysis to estimate the seismic performance of the bridge. Furthermore, fragility curves are developed for the bridge to estimate the damage state for specific seismicity. The study shows that the bridge is vulnerable to Zone IV seismicity and needs some retrofitting in specific locations such as the pier–abutment joints.

**Keywords** AVT · OMA · Masonry · Fragility curves · Arch · Bridge · Nonlinear · Seismic assessment

## 1 Introduction

The Kalka Shimla Mountain Railway line was built during British rule in India to connect Shimla (the summer capital of British India) to the rest of the country. The rail network holds the Guinness World Record for its 96 km steep rise at an altitude more than 2000 m on the Himalayas located in the state of Himachal Pradesh, India. The Kalka Shimla Mountain Railway line opened in 1903 for public traffic, making it 118 years old. In 2008, it was listed as one of the “Mountain Railways of India” and recognized by UNESCO as a World Heritage Site [1]. The key features of the Kalka Shimla Mountain Railway line are its masonry bridges with the absence of girders. This railway line has

864 small and large bridges [2] among which 42 are large bridges constructed as multi-arched galleries like ancient Roman aqueducts. Table 1 summarizes the most notable bridges of this railway line.

### 1.1 Motivation of the study

Despite their magnificent monumental features, these bridges are at risk of earthquakes (they are located in Zone IV of the seismic zoning map of India) due to the presence of Indian and Eurasian plates [3, 4]. Because this area has previously experienced devastating earthquakes such as the Kangra Earthquake ( $M_w$  7.8, 1905), Uttarkashi Earthquake ( $M_w$  7, 1991), and Chamoli Earthquake ( $M_w$

✉ Madappa V. R. Sivasubramanian, madappa@nitpy.ac.in | <sup>1</sup>Department of Civil Engineering, NIT Puducherry, Karaikal, Puducherry 609609, India. <sup>2</sup>Department of Civil Engineering, BITS Pilani, Pilani, Rajasthan 333031, India.



**Table 1** Masonry arch bridges of Kalka Shimla mountain railways

S. nos.	Name of the bridge	Special feature	Location
1	Bridge No. 541	Four-storied arch gallery bridge of height about 23 m	Near Kanoh railway station
2	Bridge No. 493	Three-storied arch gallery bridge of height about 17 m	Near Kandaghat railway station
3	Bridge No. 226	Longest arch gallery bridge of length 99 m	Near Sonwara railway station

6.8, 1999) [3], we aimed to assess the seismic vulnerability of the bridges on the Kalka Shimla Mountain Railway line.

## 1.2 Past studies

Neilson and DesRoches [5] developed a methodology for developing fragility curves for highway bridges that accounted for the fragility of the individual components of the bridge. The study concluded that the method is an effective means of decreasing the epistemic uncertainty in the analysis. Pela et al. [6] discussed a numerical modelling procedure for two masonry arch bridges and a nonlinear static analysis methodology for the seismic assessment of bridges. Pela et al. [7] compared the seismic assessment procedures used to analyse a heritage masonry arch bridge. The study concluded that the results of nonlinear static analyses are more conservative than time history analyses and can be used for seismic assessment. Pan et al. [8] developed the retrofit strategy for steel girder bridges in New York by adopting fragility analysis. The study concluded that retrofitting consisting with elastomeric bearing is more effective at reducing damage to piers. Zampieri et al. [9] proposed a new approach for the derivation of the fragility curves of clusters of masonry arch bridges. However, the methodology is only applicable to specific earthquake scenarios. Scozzese et al. [10] investigated the problem of flood-induced scour on Rubbianello Bridge. The authors performed an ambient vibration test (AVT) and operational modal analysis (OMA) as a field study and calibrated the developed numerical model for the analysis. The results showed the scour action effect on the bridge and need for OMA monitoring. Ayutulun et al. [11] carried out the seismic assessment of a railway bridge in Turkey using finite element (FE) analysis. The bridge was modelled using the macro-modelling approach and calibrated through system identification. Further, nonlinear static analysis and nonlinear time history analyses were performed. The study concluded that the nonlinear static analysis provided the same results as the nonlinear time history analysis. Zampieri et al. [12] compared the modelling strategies of masonry arch bridges for seismic assessment. The study concluded that the fibre beam element approach underestimates the horizontal stiffness

of the bridge and that the nonlinear kinematic analysis shows different results from those of conventional seismic analysis. Further, a comprehensive literature review on the development of fragility curves was performed by Billah and Alam [13]. De Risi et al. [14] developed a strategy for the development of fragility curves for an old reinforced concrete bridge in Italy, using cloud analysis and incremental dynamic analysis. The results from the each analysis were the same. However, using the pier-to-pier methodology for developing fragility curves was found to be more efficient. Lee and Nguyen [15] assessed the influence of lead rubber bearing on the seismic vulnerability of a steel bridge by generating fragility curves. The study revealed that lead rubber bearing can be used to reduce the seismic vulnerability of a bridge. Further, seismic isolation-equipped bridges can mitigate major damage to bridge structures.

## 1.3 Past studies in India

Peña et al. [16] studied the Qutub Minar (a tall brick minaret structure) to assess seismic behaviour by performing nonlinear static and dynamic analyses and by developing analytical models based on the vibration testing results. The authors concluded that the developed models are reliable for assessing seismic vulnerability. Shrestha et al. [17] investigated the seismic vulnerability of ancient masonry buildings in Nepal. Linear dynamic analysis and pushover analysis were performed. The results were compared with the damage observed during the 2015 Gorkha Earthquake. The study concluded by providing guidelines for repair and retrofit procedures for damage to ancient masonry structures. Tripathi and Rai [18] studied the seismic vulnerability of monastic temples in Sikkim using FE analyses. As a part of the study, pushover analysis was performed and fragility curves were generated. Tomar et al. [19] investigated the efficiency of fibre-reinforced polymer-based retrofitting for an old masonry building in Dehradun that suffered extensive damage during the Uttarkashi Earthquake. Roland et al. [20] investigated the seismic vulnerability of the gopurams and mandapams of the Ekambareswarar Temple in Kancheepuram, southern India. Linear dynamic analysis, nonlinear static analysis, and nonlinear dynamic

analysis were performed in an FE-based model. The study concluded by suggesting some retrofit strategies for mandapams and checking the safety of other structures. Other notable studies that include the structural analysis and evaluation of the condition of heritage structures in India have also been conducted [21–25].

#### 1.4 Objective of the present study and structure of the paper

This research investigates the seismic vulnerability of Bridge No. 541 on the Kalka Shimla Mountain Railway line and delivers probabilistic-based damage levels for zone-specific seismic demand in terms of fragility curves. To accomplish this objective, a visual survey of the structure is first conducted, which is presented in Sect. 2. Next, the system identification of the bridge structure is performed using an AVT and OMA, as described in Sect. 3. Further, an FE model for the bridge structure is developed and updated using the results obtained from the AVT and OMA, which is discussed in Sect. 4. Furthermore, pushover analysis is performed on the updated FE model to assess the seismic capacity of the bridge structure, as elaborated on in Sect. 5. Section 6 discusses the nonlinear dynamic analysis of the bridge. The probabilistic-based fragility curves are derived for specified damage levels in Sect. 7. Finally, Sect. 8 discusses the conclusions of the study.

## 2 Visual survey and details of Bridge No. 541

Bridge No. 541 is located near Kanoh railway station at an altitude of 1650 m from the mean sea level. This bridge is the tallest among all the bridges on the Kalka Shimla Mountain Railway line, with a height of 23.8 m in four stages. The main load-carrying feature of the bridge is through the arches present in all the stages. The structural components (arches, piers, and walls) are constructed with cut stones joined with lime mortar. Since there is no documentation available about the repair and retrofit of the bridge, a visual inspection was carried out to understand the current status of its structure, finding that the bridge has no sign of any major repair, retrofit, or modifications. Further, it has no damage. Moreover, all the structural elements are intact and there is no soil erosion at the bottom of the piers or abutments. Thereafter, field measurements were taken and geometric drawings were prepared. The length of the bridge is 52 m situated at the reverse curve of 48°. The typical span of the major arches is 3 m in Stage 4, 2.6 m in Stage 3 and Stage 2, and 2.2 m in Stage 1. Photographs and complete geometric details of the bridge are provided in Fig. 1.

## 3 System identification of the bridge

### 3.1 Ambient vibration testing (AVT)


AVT is a nondestructive test, generally performed to capture the acceleration response of a structure for ambient vibrations [26]. AVT on the bridge is performed in November 2019. The vibration test setup includes four uniaxial accelerometers (Meggitte Endevco 41A19), a six-channel data acquisition system (OROS 35), and four low-noise cables (approximate length 30 m each). The minimum frequency and sensitivity of the accelerometer are 1 Hz and 1 V/g, respectively. The frequency range chosen for each measurement is 0–50 Hz following the literature [27]. The ambient vibration measurement is carried out by deploying accelerometers in 37 sets. The data are recorded using OROS NVGATE software. While measuring, two accelerometers are kept as reference accelerometers and two are used as roving accelerometers. AVT is conducted under ambient vibrations and train-induced excitations. Accelerations at selected points (see Fig. 2) on the deck of the bridge are measured. The selected points are instrumented to measure the accelerations in the horizontal and vertical planes.

### 3.2 Operational modal analysis


OMA procedures estimate the system identification (i.e., the estimation of the dynamic parameters) of a structure by exploiting the data acquired through AVTs. The AVT results show that the bridge is vibrating majorly due to train-induced excitations. Thus, the modal identification of the bridge structure is performed considering the accelerations mainly induced by the vibrations of moving trains. The modal parameters are estimated from the acquired acceleration data in the frequency domain using the frequency spatial domain decomposition technique [28] and adopting OROS MODAL ANALYSIS software [29]. The analysis of the horizontal and vertical accelerations recorded on the bridge leads to the identification of three fundamental modes in a frequency range between 0 and 24 Hz. The results of the OMA in terms of natural frequencies are summarized through the modal identification function (MIF) presented in Fig. 3. The modal identification function represents the average trend of the first singular values of the spectral matrices of the recorded horizontal and vertical accelerations. The peak values in the curve of the first singular value allow the identification of natural frequencies, in which the corresponding singular values represent an estimate of the associated mode shapes. Further, Fig. 5 presents the identified mode shapes of the bridge through the OMA. The first three fundamental frequencies



(a) Photograph of Bridge No. 541, Kalka Shimla Mountain Railways




(b) Plan



(c) Elevation

Fig. 1 Photographs and geometric details of Bridge No. 541, Kalka Shimla mountain railways (all units are in meters)





Horizontal direction → Reference accelerometer • →

Vertical downward direction •

Fig. 2 Placement of the accelerometers on the bridge during AVT

**Fig. 3** Modal identification function estimated by FSDD for bridge



**Fig. 4** FE model of the Bridge No. 541, Kalka Shimla mountain railways

are estimated as 4.65 Hz, 11.38 Hz, and 23.87 Hz. The first two modes are out-of-plane modes along the longitudinal axis with bending characteristics, whereas the third mode is identified as a vertical mode. Moreover, the asymmetry in the first mode shape is due to the skewness of the bridge along the longitudinal axis.

## 4 FE modelling and model updating

### 4.1 Geometric modelling

The geometry of heritage masonry structures is complex. Hidden structural elements can be present in the structure, and these have to be determined. Numerical modelling becomes valuable only when the precise geometry of all the structural elements is integrated into the numerical model. In the present study, an FE model of the bridge is developed in commercial FE software (ABAQUS 6.21) [30], as presented in Fig. 4. To model the different elements of the selected bridge structure, a comprehensive visual survey was performed, which was discussed in Sect. 2. Further,

the FE model considers different structural elements based on the geometry discussed in Sect. 2 and shown in Fig. 1. The bridge structure has different structural parts such as arches, walls, and piers with different dimensions. These structural parts are modelled with precise geometry separately and then merged by adopting TIE constraints to create a complete FE model of the bridge.

### 4.2 Boundary condition

The bridge is located in a valley between two hills that have solid rock strata (see Fig. 1). These hills are composed of hard and stiff limestone rocks, which provide hard strata for the bridge. Therefore, the fixed boundary condition is applied at the bottom of the piers. Further, the bridge consists of a rigid abutment at both ends. Thus, a fixed boundary condition is again applied on the side of the walls of the bridge.

### 4.3 Mesh generation

The selection of element and mesh size plays a vital role in the reliability of FE models. This study uses 3D continuum shell elements for the modelling, which discretizes all the three-dimensional bodies by determining the thickness from the element nodal geometry. Further, these elements include the effects of transverse shear deformation and thickness change. The arches are modelled using standard linear S4R (four-noded quadrilateral, with reduced integration and large strain formulation), which is a three-dimensional, doubly curved, four-node shell element with six degrees of freedom per node that uses bilinear interpolation. The piers and walls of the bridge are modelled as standard linear S3R (three-noded triangular, with reduced integration), which is three node shell element having six degrees of freedom per node.

The optimum mesh size is an important factor for estimating the accurate response of the numerical model. For our purpose, mesh sensitivity analysis is performed to adopt the optimum mesh size of the selected elements of the structure. In this study, multiple modal analyses are performed on the FE model with different mesh sizes of elements [31]. The results of the mesh sensitivity analysis show that mesh sizes of 100 mm for arch elements and 300 mm for wall and pier elements are optimum. Finally, the complete FE model consists of 8742 elements connected through 5583 nodes.

#### 4.4 Modelling strategy

To analyse masonry arch bridges, the accuracy of the numerical prediction depends on the modelling strategy followed. Lourenço [32] provided a comprehensive review of the modelling strategy for masonry structures. While different strategies are available for the different complexities of a structure, a simple strategy may suffer from the overestimation of the load-carrying capacity. Conversely, advanced strategies usually suffer from the high computational cost incurred to provide the necessary details of the selected parameters [32]. This study follows the macro-modelling strategy for masonry bridges in which the isotropic material behaviour and continuum material response are assumed. This strategy is more convenient and reliable for analysing complex stone masonry structures than strategies such as the micro-modelling strategy and homogenized model strategy [31]. The drawback of this strategy is that the assumption of isotropic and homogeneous material does not reflect the anisotropic behaviour of stone masonry. However, this strategy is computationally sufficient to predict accurate results [17, 19, 32–36].

#### 4.5 Material modelling

In the case of heritage structures, the estimation of the accurate mechanical properties of the material becomes difficult because masonry structures exhibit a composite nature in bonding, joint behaviour, and true behaviour [31]. Further, in situ testing and destructive testing for the mechanical characterization of material are expensive and difficult, as there is large variability in the test results of masonry materials due to changes in sample core as well as the constitution of the structural elements [32].

In this study, preliminary data are first collected from the Northern Railway, showing that the whole bridge is constructed with limestone blocks joined with lime mortar. Moreover, due to the importance of heritage, no minor or major destructive testing is allowed on the bridge. To solve this difficulty, a comprehensive review is performed

to estimate the material mechanical characteristics of the limestone masonry. After the review, the initial values of Young's modulus, density, and the Poisson ratio are adopted as 10,000 MPa, 2500 kg/m<sup>3</sup>, and 0.2, respectively for the bridge structure, as recommended by Fanning and Boothy [37].

#### 4.6 Numerical modal analysis

In this study, a numerical modal analysis is performed on the developed FE model to estimate the dynamic properties of the bridge. In ABAQUS, the frequency step is selected and the Block Lanczos method is chosen for the modal extraction. The results of the numerical modal analysis are shown in Fig. 5. Further, the mode shape and associated natural frequency estimated from the initial FE model are compared with the experimental results in Fig. 5. The numerical modal analysis results show the good correlation of the initial FE model mode shapes with the experimental mode shapes, but differences in the associated natural frequencies.

#### 4.7 FE model updating

FE model updating is a procedure for calibrating the existing numerical model by incorporating the results obtained from AVTs and OMA. An existing FE model can only account for the initial geometric and material properties. However, in the case of heritage structures, it becomes necessary to update the numerical model to account for the current conditions and provide an accurate structural assessment. In general, FE model updating can be achieved by adjusting the physical properties, mechanical properties, boundary conditions, masses, restrained properties, joint properties, and geometry of the elements in the numerical model to match the results obtained from the AVT and OMA [26].

In this study, to reduce the differences between the dynamic parameters in the FE model and experimental results, a manual model updating procedure is adopted based on engineering guidelines. Mechanical properties such as Young's modulus and density are modified in the developed FE model to match the natural frequencies obtained from the AVT and OMA. The model updating shows an average difference in natural frequencies of 3–8%. The initial and updated material properties adopted for the bridge structure are presented in Table 2. Further, Table 3 compares the initial and updated frequencies with the experimental results for the bridge.




Fig. 5 Comparison of experimental mode shapes and initial analytical mode shapes

Table 2 Initial and updated material property

Material	Parameter	Initial value	Updated value	Difference (%)
Stone masonry	Young's modulus (MPa)	10,000	9600	4.0
	Density (kg/m <sup>3</sup> )	2500	2200	12.0

Table 3 Results of numerical modal updating

Modes	Frequency (Hz)				
	Experimental	Initial model	Initial error (%)	Updated model	Final error (%)
Mode-1	4.65	4.28	8.10	4.60	1.02
Mode-2	11.38	11.10	2.56	11.66	2.46
Mode-3	23.87	22.63	5.24	23.84	3.33

## 5 Pushover analysis

### 5.1 Constitutive material model

The inelastic behaviour of stone masonry is examined by employing the concrete damaged plasticity model [38, 39] available in the ABAQUS FE environment. The constitutive model applied in the analysis simulates both the cracking and the crushing of the material by plastic rules. Although the model was developed for isotropic material such as concrete, several works show that it is reliable for the analysis of stone masonry [34, 36]. The dilation angle value is kept at  $20^\circ$  assuming that the stone masonry has regular units of stones. The value adopted for the flow potential eccentricity is 0.1, which is the default value. The ratio between the biaxial and uniaxial compression strengths is considered as 1.16, the Drucker–Prager surface modifier is kept as 0.667, and the viscosity parameter is selected as 0.01 because the effect of these parameters is negligible on the global response of the structure.


The experimental study is conducted based on the limestone masonry samples of Veríssimo-Anacleto et al. [40], who proposed a stone masonry compression strength of 7.5 MPa, which is adopted in the present study. The tensile material strengths  $f_t$  are assumed to be  $1/10$  [41] of the compression strengths  $f_c$  suggested by previous research. The feasible values of fracture energy  $G_f$  are obtained by multiplying the tensile strengths by the ductility index  $G_f/f_t = 0.064$  mm proposed by Compán et al. [41] for stone masonry. In the compression, a compression damage parameter is avoided by assuming the fully plastic behaviour of the material. Further, a nonlinear law (stress equal to  $0.8 \cdot f_c$  at a 0.5% plastic strain) is followed, as proposed by

Acito et al. [34]. Figure 6 shows the adopted behaviour of the stone masonry in compression and in tension.

### 5.2 Pushover analysis procedure

The seismic behaviour of the bridge structure is investigated using pushover analysis. The forces are applied in the transverse direction of the structure to determine its capacity. The selection of the load pattern in pushover analysis plays a vital role in predicting the average response of the structure [42]. When performing a pushover analysis of masonry structures, PERPETUATE guidelines [43] suggest that two or more load distribution patterns should be adopted to acquire an accurate response. Since the mass of masonry structures is distributed nonuniformly, a mode shape proportional force distribution load pattern cannot be adopted for the seismic evaluation [25, 43]. Moreover, studies suggest that the mass-based force distribution load pattern provides more reliable results for seismic evaluation [6, 44]. In the present study, two load distribution patterns are followed to perform the pushover analysis. The first pattern is proportional to the masses of the structures (Uniform) and the second pattern is directly proportional to the product of the masses and height of the structures (Triangular) [43]. The lateral loads are applied to the structural model in the transverse direction (Y direction). Thus, the load distribution provides the comprehensive seismic capacity and performance of the bridge structure for the given seismicity.

The control node is that selected for reading the displacement during analysis. Further, it represents the response of the whole structure during the analysis. The control node has been kept at the top of the bridge structure in past studies [43, 45, 46]. In this study, the control



**Fig. 6** Stone masonry behavior (a) in tension (b) in compression



node is selected at the top of the middle arch (see Fig. 4), where the recorded vibrations are found to be higher than in other locations. Four analyses are performed with two load distribution patterns in the +ve Y and -ve Y directions. The capacity spectrum method [47] is adopted to convert the pushover curve into a capacity curve to evaluate the seismic performance of the structure. The evaluation for spectral acceleration  $S_a$  is given in Eq. 1, where  $V_b$  is the base shear,  $W$  is the total weight of the bridge structure,  $M_k$  is the modal mass participation for the  $k$ th mode,  $M$  is the mass of the bridge structure, and  $g$  denotes acceleration due to gravity. Further, spectral displacement ( $S_d$ ) is calculated as shown in Eq. 2, where  $\Delta$  is the control node displacement,  $P_k$  is the modal participation factor for the  $k$ th mode, and  $\phi_k$  is the modal amplitude for the  $k$ th mode. Further, the demand curve is derived from the response spectrum for Zone IV seismicity following IS 1893:2016 [4] for the rock soil profile adopting procedures given in FEMA 440 [48]. The performance point is

evaluated from the demand and capacity curve (point of intersection), which denotes the state of the structure in a representative earthquake event.

$$S_a = \frac{V_b/W}{M_k/M}g \tag{1}$$

$$S_d = \frac{\Delta}{P_k \phi_k} \tag{2}$$

Figure 7 shows the pushover curve obtained for the bridge structure concerning the loading conditions in both the +ve Y direction and the -ve Y direction. This figure shows that the structure has more capacity for a uniform loading pattern than the triangular loading pattern in both directions. Further, the capacity of the bridge structure is slightly more in the -ve Y direction than in the +ve Y direction for load patterns. This is as expected due to the skewness of the bridge, which provides more stiffness to the structure in the lateral direction.

Figure 8a shows seismic demand by plotting the response spectra of different seismic zones for the rock soil profile, and Fig. 8b plots the capacity curve obtained from




Fig. 7 Pushover curve for different load distribution

Table 4 Performance points obtained from the demand and capacity curve

S. nos.	Load distribution	Spectral acceleration (g)	Spectral displacement (m)
1	Uniform load +ve Y direction	0.18	0.058
2	Uniform load -ve Y direction	0.20	0.054
3	Triangular load +ve Y direction	0.15	0.070
4	Triangular load -ve Y direction	0.17	0.066






Fig. 8 a Design response spectra as per Indian code for different seismic zones, b performance of the bridge in Zone IV seismic demand

**Fig. 9** Tension damage state of the Bridge No. 541, Kalka Shimla Mountain Railways at performance point (red—highest tension damage, blue—lowest tension damage)




the pushover analysis along with the demand spectrum of Zone IV seismicity. The performance points in Fig. 8b for the different load distributions are also presented in Table 4. Further, Fig. 9 shows the tension damage of the bridge at the performance point for a uniform load distribution. The tension damage shows that the cracks originated from the pier–abutment joints and propagated to the arch-to-pier joints. The most vulnerable parts are the pier-to-arch joints from which the cracks are expected to propagate. Moreover, Bridge No. 541 of the Kalka Shimla Mountain Railway line shows out-of-plane bending behaviour of the pier–abutment joints for seismic forces.

### 6 Nonlinear dynamic analysis

The nonlinear dynamic analysis is performed to capture the response of the structure. The inelastic response of the heritage structure estimated through the nonlinear dynamic analyses is reliable [44]. Further, nonlinear dynamic analysis provides a more realistic response of the heritage structure for selected ground motions. Thus, nonlinear dynamic analysis should be performed for heritage structures.

The nonlinear dynamic analyses are performed in ABAQUS software. In the first step, the gravity loads are applied to the model. Then, explicit analysis procedures are selected for the dynamic analysis to avoid large distortions and localized strains. Further, the acceleration of the selected ground motion records is applied at the base of the model in the transverse direction. Additionally, the energy dissipation in the numerical model is incorporated using the hysteretic behaviour of the materials. Moreover, a structural viscous damping proportion of 5% is chosen for the analysis.

In this study, five ground motion records are adopted to simulate the seismic load on Bridge No. 541 of the Kalka Shimla Mountain Railway line. For this purpose, ground




**Fig. 10** Scaled response spectra of selected ground motions and target response spectrum for Zone IV seismicity

**Table 5** Description of ground motions

S. no	Name of the earthquake	Year	Recording station	PGA (g)
1	Chi-chi	1999	Tcu045	0.361
2	Imperial valley	1979	USGS station 5115	0.315
3	Kobe	1995	Kakogawa (cue90)	0.344
4	El Centro	1940	El Centro	0.341
5	Bhuj	2001	Bhuj	0.303

motion records are selected from the PEER Strong Motion Database [43]. To scale the selected ground motion, the target spectrum is selected from IS 1893:2016. The following scaling parameters are assumed: (1) the ground is selected as a rock profile and (2) the intensity of the records is selected as 0.24 g (for Zone IV seismicity). Figure 10 shows the coherence between the square root of the sum of the squares of scaled response spectra of the




**Fig. 11** Selected ground motion records of the earthquake

selected ground motion and target spectrum. Moreover, the details of the selected ground motion records are given in Table 5. The compatible accelerograms of the selected ground motions are also shown in Fig. 11.

Figure 12 presents the displacement of the control node of the bridge structure after the nonlinear dynamic analyses. The maximum displacement of the control point is recorded as 0.55 m for the Imperial Valley ground motion. The tension damage contours of the structure at the

**Fig. 12** Control point horizontal direction displacement for Bridge No. 541, Kalka Shimla mountain railways



practical end of the simulations for the transversal seismic action are depicted in Fig. 13. Moreover, the contour plots of the tension damage parameters are red to represent full damage and blue for less damage. Further, when seismic excitation is applied along the transverse direction of the bridges, the active failure mechanism is the overturning of the bottom piers, with a clear detachment from the abutment walls that show an out-of-plane bending action at the pier–abutment joint.

The pushover analysis and nonlinear dynamic analysis show the similar behaviour of the bridge in terms of damage distribution. The tension damage distribution of the bridge is similar in both analyses, with the crack propagation starting from the pier–abutment joint and propagating further. However, as comparing the whole displacement of the time history results with those from the pushover analysis is challenging, the maxima displacement of the time history analysis is compared with the displacement estimated using the performance point of the pushover analysis. The results show that the average displacement obtained from the time history analysis is 0.40 m, which is more than that observed in the pushover analysis (0.070 m). This shows that the pushover analysis produces more conservative results than the nonlinear time history analysis. Thus, the results obtained from the pushover analysis can be taken into consideration to estimate the fragility curves of the bridge structure.

The pushover analysis and nonlinear dynamic analysis showed the similar behaviour of the bridge in terms of damage distribution. The tension damage distribution of the bridge is fairly same for both the analyses as we can see that the crack propagation is starting from the pier abutment joint and propagating further. Further, it is not possible to compare the whole displacement of time history results with pushover analysis. For this purpose, the maxima displacement of time history analysis is

compared with the displacement estimated by the performance point of the pushover analysis. The results showed that the average displacement of the obtained from time history analysis is 0.40 m which is more than that of observed in push-over analysis, i.e., 0.070 m. This shows that the pushover analysis produces conservative results as compared to nonlinear time history analysis. Thus, the obtained results from the pushover analysis can be taken into consideration for estimating the fragility curve of the bridge structure.

## 7 Fragility analysis

In the case of heritage structures, a probabilistic approach is necessary to evaluate seismic vulnerability. Fragility analysis describes the probability of the exceedance of a structure being damaged beyond a damage level for a given ground motion intensity. In addition, fragility curves provide details on the potential loss resulting from the specific intensity of an earthquake. Different procedures are available in the literature for developing fragility curves [18, 43, 49–53]. This research uses the pushover curve to generate the fragility curves to assess seismic vulnerability. Pushover analysis is a basic practical tool for evaluating the seismic response. This methodology is adopted for its simplification and reliability when estimating the damage that has occurred for a specified seismicity. Significant advances in the development of fragility curves for heritage structures have been made [35, 43, 46, 51, 52, 54]. The details of the methodology adapted to generate the fragility curve from the pushover analysis for the heritage bridge structure are described next.




Fig. 13 Tension damage contours from different time histories for Bridge No. 541, Kalka Shimla mountain railway





Fig. 14 **a** Pushover curve with different damage levels [43], **b** damage contours at different damage levels

Table 6 Damage levels for the bridge structure

Damage level	Displacement	Description
Damage level 1 (DL-1)	$d_{DL1} = 0.112 \times d$	Distress between the pier–abutment joint with mild damage
Damage level 2 (DL-2)	$d_{DL2} = 0.16 \times d$	Distress in the arch–pier joints. Minor distress in the pier–abutment joints
Damage level 3 (DL-3)	$d_{DL3} = 0.25 \times d$	Severe distress in some arch, pier, and abutment joints
Damage level 4 (DL-4)	$d_{DL4} = 0.40 \times d$	Tension damage at the bottom of the piers and large movement of the joints between walls, piers, and abutments

### 7.1 Definition of damage levels

For the fragility analysis, it is necessary to establish the appropriate damage levels associated with different states of the structure from a service state to a collapse state. In this study, four damage levels for the bridge structure are considered following Lagomarsino and Cattari [43] based on the approach that damage levels can directly defined on the pushover curve using approximate limits. Figure 14 shows the damage level defined on the pushover curve and different damage states, which are explained in Table 6.

### 7.2 Fragility curves for the bridge structure

The fragility curves for the bridge structure are developed following the procedure proposed by Shinozuka et al. [55] for different expected peak ground acceleration (PGA) values in the state of Himachal Pradesh. The steps followed to develop the fragility curves are below:

*Step 1* The average demand spectrum ( $m$ ) and average demand spectrum  $\pm$  standard deviation ( $\sigma$ ) [37] are calculated from the response spectra available in IS 1893:2016 (Part1) for the specific zone [4].

$$S_a = \frac{V_b/W}{M_k/M}g \tag{1}$$

$$S_d = \frac{\Delta}{P_k \theta_k} \tag{2}$$

*Step 2* The capacity curve of the bridge structure (calculated from the pushover curve, as mentioned in Eqs. 1 and 2) intersects the three abovementioned demand spectra and yields the three performance points that determine the spectral displacement  $S_d(a)$  of the performance point, as shown in Fig. 15.

*Step 3* The lognormal distribution parameters  $C(a)$  and  $\zeta(a)$  of spectral displacement  $S_d(a)$  are calculated from Eqs. 3 and 4 as detailed by Shinozuka et al. [55]:

$$S_d(a) = C(a) \exp \left[ \frac{\{\zeta(a)\}^2}{2} \right] \tag{3}$$

$$\{\sigma_d(a)\}^2 = \{S_d(a)\}^2 [\exp \{\zeta(a)\}^2 - 1] \tag{4}$$

Once  $C(a)$  and  $\zeta(a)$  are determined for the bridge, the probability of exceeding the said displacement of a particular damage level  $d_{DL}$  is

$$P[S_d(a) > d_{DL}] = 1 - \Phi \left[ \frac{\ln \left( \frac{d_{DL}}{C(a)} \right)}{\zeta(a)} \right] \text{ where } \Phi \left[ \frac{\ln \left( \frac{d_{DL}}{C(a)} \right)}{\zeta(a)} \right] \text{ is the standard normal distribution function} \tag{5}$$





Fig. 15 Performance point of the structure for specific demand

The abovementioned procedures are also followed to develop the fragility curves for different PGA values. In this study, the fragility curves are plotted for the probability of the exceedance of different specified damage levels against the PGA value of different seismic zones: a PGA value of 0.1 g for Zone II, PGA value of 0.16 g for Zone III, and PGA value of 0.24 g for Zone IV seismicity.

### 7.3 Results and discussion

Figure 16 shows the developed fragility curves for Bridge No. 541 of the Kalka Shimla Mountain Railway line for two load distributions (uniform and triangular) in the  $\pm Y$  direction. The fragility curves are plotted for different PGA values of seismic Zone II to Zone IV against the defined damage levels (DL-1 to DL-4). The figure shows that for Zone II seismicity, the bridge structure is vulnerable only to the DL-1 damage level, which means it can withstand Zone II seismicity with mild damage. Further, the bridge structure is more susceptible to DL-2 against Zone III seismicity with considerable damage. On the other hand, the probability of exceeding DL-3 and DL-4 is relatively insignificant for



**Fig. 16** Fragility curves for Bridge No. 541, Kalka Shimla mountain railways

Zone II and Zone III seismicity. In addition, a significant rise in the probability of exceeding DL-3 for Zone IV seismicity is observed. Therefore, seismic retrofit strategies for the bridge structure are required to protect against Zone IV seismicity. Furthermore, the fragility curves show that the probability of the exceedance of DL-4 is insignificant for all seismic zones (below 0.3). Moreover, when the developed fragility curves are compared for the different load distributions, triangular loading shows a higher probability of exceedance for DL-1, DL-2, and DL-3, whereas a negligible difference is observed for DL-4 in the fragility curves based on the different load distributions.

### 8 Conclusions

In this study, an FE model of Bridge No. 541 of the Kalka Shimla Mountain Railway line is prepared and updated using results from the AVT and OMA. Further, the capacity of the structure is evaluated by performing a pushover

analysis and the seismic vulnerability of the bridge is assessed against zone-specific seismicity by developing fragility curves. The following conclusions are drawn:

- A requirement for building a reliable FE model was satisfied by updating the initial FE model with the results of the AVT and OMA. The FE model updating procedure involved the modification of elastic material properties such as Young’s modulus and density based on engineering guidelines, which proved to be acceptable to correlate the current condition of the bridge structure in terms of material degradation due to the operational condition of the bridge as well as environmental effects.
- The performance assessment of the bridge structure was carried out for Zone IV seismicity with a rock soil profile by comparing the demand and capacity of the bridge structure. It was observed that the bridge has adequate strength against Zone IV seismicity with light damage to arches and piers. Additionally, the



bridge structure is susceptible to damage to the joints between piers and abutments. Further, the cracks originate from the abutment–pier joints and progress towards the arches.

- Nonlinear dynamic analysis provided more information on the seismic behaviour of the bridge structure. The displacement demand observed in the analysis was higher than that of pushover analysis. Further, the results showed good correlation with the pushover analysis results in terms of the tension damage contours.
- The fragility analysis provided the seismic performance of the bridge structure against different damage levels for different zone-specific seismicity. From the fragility analysis, the probability of a DL-3 damage level occurring during an earthquake of Zone IV seismicity was expected to be very high. Further, fragility curves were found to be more convenient for understanding the seismic vulnerability of the masonry bridge.
- The results of this study could be validated in future research by estimating the damage states using incremental dynamic analyses.

**Acknowledgements** This paper is an outcome of the author's PhD work enrolled at National Institute of Technology Puducherry. Authors are thankful to the National Institute of Technology Puducherry for providing computational facilities. Further, authors acknowledge Northern Railways, Government of India for permitting to conduct the field study. Lastly, the authors are grateful to Shimla Division, Northern Railways, Government of India for providing accommodations and manpower throughout the field study.

**Funding** This research study is sponsored by Seismology Division, Ministry of Earth Sciences, Government of India (Ref. No.: MoES/P.O.(Seismo)/1(296)/2016) sanctioned to Co-authors. The second author is the main supervisor of this study.

#### Declaration

**Conflict of interest** The authors declare that they have no competing interests.

**Open Access** This article is licensed under a Creative Commons Attribution 4.0 International License, which permits use, sharing, adaptation, distribution and reproduction in any medium or format, as long as you give appropriate credit to the original author(s) and the source, provide a link to the Creative Commons licence, and indicate if changes were made. The images or other third party material in this article are included in the article's Creative Commons licence, unless indicated otherwise in a credit line to the material. If material is not included in the article's Creative Commons licence and your intended use is not permitted by statutory regulation or exceeds the permitted use, you will need to obtain permission directly from the copyright holder. To view a copy of this licence, visit <http://creativecommons.org/licenses/by/4.0/>.

## References

1. ICOMOS (2008) Technical Evaluation Mission: 11-16 September 2008, 911:11–16, Paris, France
2. Mathur (2008) Bridges, buildings and black beauties of northern railway. Institute of Rail Transport in association with National Rail Museum, India
3. Chandra U (1992) Seismotectonics of Himalayas. *Curr Sci* 62:40–71
4. BIS (2016) IS 1893: 2016—Indian standard criteria for earthquake resistant design of structures, part 1: general provisions and buildings, New Delhi, India
5. Nielson B, DesRoches R (2007) Seismic fragility methodology for highway bridges using a component level approach. *Earthq Eng Struct Dynam* 36:823–839. <https://doi.org/10.1002/eqe>
6. Pelà L, Aprile A, Benedetti A (2009) Seismic assessment of masonry arch bridges. *Eng Struct* 31(8):1777–1788. <https://doi.org/10.1016/j.engstruct.2009.02.012>
7. Pelà L, Aprile A, Benedetti A (2013) Comparison of seismic assessment procedures for masonry arch bridges. *Constr Build Mater* 38:381–394. <https://doi.org/10.1016/j.conbuildmat.2012.08.046>
8. Pan Y, Agrawal AK, Ghosn M, Alampalli S (2010) Seismic fragility of multispan simply supported steel highway bridges in New York state. I: Bridge modeling, parametric analysis, and retrofit design. *J Bridge Eng* 15(5):448–461. [https://doi.org/10.1061/\(asce\)be.1943-5592.0000085](https://doi.org/10.1061/(asce)be.1943-5592.0000085)
9. Zampieri P, Zanini MA, Faleschini F (2016) Derivation of analytical seismic fragility functions for common masonry bridge types: methodology and application to real cases. *Eng Fail Anal* 68:275–291. <https://doi.org/10.1016/j.engfailanal.2016.05.031>
10. Scozzese F, Ragni L, Tubaldi E, Gara F (2019) Modal properties variation and collapse assessment of masonry arch bridges under scour action. *Eng Struct* 199(September):109665. <https://doi.org/10.1016/j.engstruct.2019.109665>
11. Aytulun E, Soyoz S, Karcioğlu E (2019) System Identification and Seismic Performance Assessment of a Stone Arch Bridge. *J Earthquake Eng* 00(00):1–21. <https://doi.org/10.1080/13632469.2019.1692740>
12. Zampieri P, Perboni S, Denis Tetougueni C, Pellegrino C (2020) Different approaches to assess the seismic capacity of masonry bridges by non-linear static analysis. *Front Built Environ*. <https://doi.org/10.3389/fbuil.2020.00047>
13. Muntasir Billah AHM, Shahria Alam M (2015) Seismic fragility assessment of highway bridges: a state-of-the-art review. *Struct Infrastruct Eng* 11(6):804–832. <https://doi.org/10.1080/15732479.2014.912243>
14. De Risi R, Di Sarno L, Paolacci F (2017) Probabilistic seismic performance assessment of an existing RC bridge with portal-frame piers designed for gravity loads only. *Eng Struct* 145:348–367. <https://doi.org/10.1016/j.engstruct.2017.04.053>
15. Lee TH, Nguyen DD (2018) Seismic vulnerability assessment of a continuous steel box girder bridge considering influence of LRB properties. *Sadhana Acad Proc Eng Sci*. <https://doi.org/10.1007/s12046-017-0774-x>
16. Peña F, Lourenço PB, Mendes N, Oliveira DV (2010) Numerical models for the seismic assessment of an old masonry tower. *Eng Struct* 32(5):1466–1478. <https://doi.org/10.1016/j.engstruct.2010.01.027>
17. Shrestha H, Dizhur D, Prajapati R et al (2017) Seismic vulnerability assessment of two nepalese rana palaces. *Earthq Spectra* 33(1):345–362. <https://doi.org/10.1193/010517EQS004M>

18. Tripathi A, Rai DC (2019) Seismic vulnerability assessment and fragility analysis of stone masonry monastic temples in Sikkim Himalayas. *Int J Archit Herit* 13(2):257–272. <https://doi.org/10.1080/15583058.2018.1433249>
19. Tomar A, Paul DK, Agarwal P (2019) Seismic assessment and retrofitting of a heritage brick masonry building using FRP. *J Earthq Tsunami*. <https://doi.org/10.1142/S179343119500015>
20. Ronald JA, Menon A, Meher Prasad A et al (2019) Modelling and analysis of South Indian temple structures under earthquake loading. *Sādhanā*. <https://doi.org/10.1007/s12046-018-0831-0S>
21. Srinivas V, Sasmal S, Ramanjaneyulu K, Ravisankar K (2014) Performance evaluation of a stone masonry-arch railway bridge under increased axle loads. *J Perform Constr Facil* 28(2):363–375. [https://doi.org/10.1061/\(ASCE\)CF.1943-5509.0000407](https://doi.org/10.1061/(ASCE)CF.1943-5509.0000407)
22. Kishen JMC, Ramaswamy A, Manohar CS (2013) Safety assessment of a masonry arch bridge: field testing and simulations. *J Bridg Eng* 18(2):162–171. [https://doi.org/10.1061/\(ASCE\)BE.1943-5592.0000338](https://doi.org/10.1061/(ASCE)BE.1943-5592.0000338)
23. Ghosh D, Gupta H, Mittal AK, Shekhar R (2017) Inspection of heritage structure using infrared thermography. In: Conference and exhibition of the Indian Society for NDT (December), Chennai, Tamil Nadu, India
24. Aranha CA, Menon A, Sengupta AK (2019) Determination of the causative mechanism of structural distress in the presidential palace of India. *Eng Fail Anal* 95(September 2018):312–331. <https://doi.org/10.1016/j.engfailanal.2018.09.023>
25. Banerji P, Chikermane S (2012) Condition assessment of a heritage arch bridge using a novel model updation technique. *J Civ Struct Heal Monit* 2(1):1–16. <https://doi.org/10.1007/s13349-011-0013-9>
26. Shimpi V, Sivasubramanian MVR, Singh SB (2019) System identification of heritage structures through AVT and OMA: a review. *SDHM Struct Durab Heal Monit*. <https://doi.org/10.32604/sdhm.2019.05951>
27. Bayraktar A, Altunişik AC, Birinci F et al (2010) Finite-element analysis and vibration testing of a two-span masonry arch bridge. *J Perform Constr Facil* 24(1):46–52. [https://doi.org/10.1061/\(ASCE\)CF.1943-5509.0000060](https://doi.org/10.1061/(ASCE)CF.1943-5509.0000060)
28. Wang T, Celik O, Catbas FN, Zhang LM (2016) A frequency and spatial domain decomposition method for operational strain modal analysis and its application. *Eng Struct* 114:104–112. <https://doi.org/10.1016/j.engstruct.2016.02.011>
29. OROS (2018) Modal Analysis Software Manual. France
30. Dassault Systemes Simulia Corporation (2014) Abaqus V. 6.14 Documentation. providence Witham, USA
31. Shimpi V, Sivasubramanian MVR, Singh SB (2018) Review on nonlinear seismic assessment of masonry structures. In: International Conference on Advances in Concrete, Structure and Geotechnical Engineering, BITS Pilani, Pilani, India
32. Lourenço PB (2002) Computations of historical masonry constructions. *Prog Struct Mat Eng* 4(3):301–319
33. Roca P, Cervera M, Gariup G, Pela L (2010) Structural analysis of masonry historical constructions. Classical and advanced approaches. *Arch Comput Methods Eng* 17(3):299–325. <https://doi.org/10.1007/s11831-010-9046-1>
34. Acito M, Bocciarelli M, Chesi C, Milani G (2014) Collapse of the clock tower in Finale Emilia after the May 2012 Emilia Romagna earthquake sequence: Numerical insight. *Eng Struct* 72(May 2012):70–91. <https://doi.org/10.1016/j.engstruct.2014.04.026>
35. Asteris PG, Chronopoulos MP, Chrysostomou CZ et al (2014) Seismic vulnerability assessment of historical masonry structural systems. *Eng Struct* 62–63:118–134. <https://doi.org/10.1016/j.engstruct.2014.01.031>
36. Valente M, Milani G (2016) Seismic assessment of historical masonry towers by means of simplified approaches and standard FEM. *Constr Build Mater* 108:74–104. <https://doi.org/10.1016/j.conbuildmat.2016.01.025>
37. Fanning PJ, Boothby TE (2001) Three-dimensional modelling and full-scale testing of stone arch bridges. *Comput Struct* 79(29–30):2645–2662. [https://doi.org/10.1016/S0045-7949\(01\)00109-2](https://doi.org/10.1016/S0045-7949(01)00109-2)
38. Lee J, Fenves GL (1998) Plastic-damage model for cyclic loading of concrete structures. *J Eng Mech* 124(8):892–900. [https://doi.org/10.1061/\(ASCE\)0733-9399\(1998\)124:8\(892\)](https://doi.org/10.1061/(ASCE)0733-9399(1998)124:8(892))
39. Lubliner J, Oliver J, Oller S, Onate E (1989) A plastic-damage model. *Int J Solids Struct* 25(3):299–326
40. Veríssimo-Anacleto J, Ludovico-Marques M, Neto P (2020) An empirical model for compressive strength of the limestone masonry based on number of courses: an experimental study. *Constr Build Mater*. <https://doi.org/10.1016/j.conbuildmat.2020.119508>
41. Compán V, Pachón P, Cámara M et al (2017) Structural safety assessment of geometrically complex masonry vaults by nonlinear analysis. The Chapel of the Würzburg Residence (Germany). *Eng Struct* 140(January 2020):1–13. <https://doi.org/10.1016/j.engstruct.2017.03.002>
42. Elnashai AS, Di Sarno L (2008) Fundamentals of earthquake engineering. Wiley, Hoboken. <https://doi.org/10.5860/choice.32-1551>
43. Lagomarsino S, Cattari S (2015) PERPETUATE guidelines for seismic performance-based assessment of cultural heritage masonry structures. *Bull Earthq Eng* 13(1):13–47. <https://doi.org/10.1007/s10518-014-9674-1>
44. Endo Y, Pelà L, Roca P (2017) Review of different pushover analysis methods applied to masonry buildings and comparison with nonlinear dynamic analysis. *J Earthq Eng* 21(8):1234–1255. <https://doi.org/10.1080/13632469.2016.1210055>
45. Bertolesi E, Milani G, Lopane FD, Acito M (2017) Augustus bridge in Narni (Italy): seismic vulnerability assessment of the still standing part, possible causes of collapse, and importance of the roman concrete infill in the seismic-resistant behavior. *Int J Archit Herit* 11(5):717–746. <https://doi.org/10.1080/15583058.2017.1300712>
46. Barbieri DM (2019) Two methodological approaches to assess the seismic vulnerability of masonry bridges. *J Traffic Transp Eng (Engl Ed)* 6(1):49–64. <https://doi.org/10.1016/j.jtte.2018.09.003>
47. Comartin CD, Rojahn C (1996) ATC 40 Seismic Evaluation and Retrofit of Concrete Buildings Redwood City California. Appl Technol Counc 1(November 1996):334
48. FEMA 440 (2005) Improvement of nonlinear static seismic analysis procedures. Federal Emergency Management Agency, Washington DC
49. Cescatti E, Salzano P, Casapulla C et al (2020) Damages to masonry churches after 2016–2017 Central Italy seismic sequence and definition of fragility curves. *Bull Earthq Eng*. <https://doi.org/10.1007/s10518-019-00729-7>
50. Rosti A, Rota M, Penna A (2020) Empirical fragility curves for Italian URM buildings. *Bull Earthq Eng*. <https://doi.org/10.1007/s10518-020-00845-9>
51. Choi E, DesRoches R, Nielson B (2004) Seismic fragility of typical bridges in moderate seismic zones. *Eng Struct* 26(2):187–199. <https://doi.org/10.1016/j.engstruct.2003.09.006>
52. Tecchio G, Donà M, da Porto F (2016) Seismic fragility curves of as-built single-span masonry arch bridges. *Bull Earthq Eng* 14(11):3099–3124. <https://doi.org/10.1007/s10518-016-9931-6>
53. Fallah Tafti M, Amini Hosseini K, Mansouri B (2020) Generation of new fragility curves for common types of buildings in Iran. *Bull Earthq Eng* 18(7):3079–3099. <https://doi.org/10.1007/s10518-020-00811-5>
54. Ronald JA, Menon A, Prasad AM et al (2018) Modelling and analysis of South Indian temple structures under earthquake

- loading. *Sadhana Acad Proc Eng Sci* 43(5):1–20. <https://doi.org/10.1007/s12046-018-0831-0>
55. Shinozuka M, Feng MQ, Kim H-K, Kim S-H (2000) Nonlinear static procedures for fragility curves development. *J Eng Mech* 126:1287–1295

**Publisher's Note** Springer Nature remains neutral with regard to jurisdictional claims in published maps and institutional affiliations.